

429 Indiana Street, March 21, 2006

Front, view from street



Front porch, rotted porch structure, flooring and roof:



South side, view from front:



South side, view from back:



Rotted – roof and supports:



429 Indiana 3/21/06 (document 2)

South side, rotted roof structure:



Southwest corner, rear of house:



Southwest corner, rotted roof



Deteriorated Foundation, South side – rear of structure



Deteriorated foundation, south wall:



Rear porch – rotted, deteriorated/damaged foundation and supports:



North side, view from rear: (rotted roof, open crawl space)

