



785 Maple, 5/01/12



Front porch - lighting



Exterior – east wall



Interior – front room



(power strip – with power – mounted above doorway)



Open stairwell to basement (front room)



Electrical panel (1st floor/west wall)



battery charger



1st floor – looking north toward back door leading into back porch area:



1st Floor – north area/interior:



Fire damaged electrical boxes in ceiling (1st floor)



Floor – 1st floor




Basement



Basement – south area:



Make-shift kitchen area in basement





'bedroom' area in basement





Basement – furnace, bathroom area:



Rear porch addition (north side)





View from west:



Porch/addition – north side – view from west:



Refrigerator – plugged in and exposed to weather





