

929 Holiday Drive, 8/18/11

Front of house (looking north, from southeast corner)



South side of house:

Front of house




Front of house, window frame rotted



North side of house – roof area:



(picture taken 8/19/11) front entry way



Front entry – exposed wiring and insulation:



Front porch roof – open and rafters are pulling away from ridge board:



Stairway – at front entry – going into basement:



Living room – plastic wrap for ceiling, mold, window frame rotted:



Living room – looking north – exterior wall open



Living room – floor is saturated/damp:



Roof structure – above living room, ridge board shifted:



Dining room wall – mold



Dining room – light fixture, water stains on joists



Kitchen ceiling, damaged electrical wiring



Bedroom (middle/east side), water damage



mold



Electrical outlet – scorched:



Electrical outlet – unsecured, insulation



**Bedroom (middle – east side) (continued)**

Ceiling



Closet



Unsecured light fixture - hallway



Bedroom (southeast)



Master bedroom closet - Ceiling — mold:



Basement:



Basement – below staircase:



Basement – family room area:



Basement – utility room area:



Rear of house, electrical service unsecured:



Hole – back exterior wall:



Sunroom – back of house:

