



Vantuyl Dr – example of power steering marks, some leading to complete loss of seal requiring minor patch



Lili Dr - example of power steering marks with loss of seal, completed with minor patching



Larissa Dr near cul-de-sac – rougher texture apparent but typical in bulb areas where there is overlap of the application passes of the surface seal machine



Example of microsurface seal with rougher texture than a roller compacted 2" mill and overlay;
Over time and with traffic, the material will tend to smooth out more



Inverness Dr – example of seal damage from aggressive vehicle turn near a temporary road closure



Inverness Dr – completed with pavement markings/ crosswalk near Quail Run Elementary



Folks Rd (south of 6th St) – example of heavy loss of material from vehicles



Folks Rd (south of 6th St) – example of heavy loss of material from vehicles



Folks Rd (south of 6th St) – after patching/ reapplication of surface seal by machine



Folks Rd (south of 6th St) – completed with pavement markings



Wagon Wheel - completed



Royal Birkdale Ct - completed



Cedar Ridge Ct - completed



Larissa Dr - completed