

1231 Pennsylvania Street, 1/30/2015, Pictures of interior

Rear porch



Doorway, leading from back porch into kitchen





Kitchen, SW room



Failing floor structure (kitchen)



Front/North room:



Floor, front/north room:



Ceiling, Front/north room - looking toward front door and doorway into the front/south room



Structural members – under front/south room:



Front / south room

ceiling rafters

