



Nieder Rd

W 33rd St

Iowa St

Iowa (frontage) St

K-10 Ramp

Armstrong Rd

Armstrong Rd

E 1300 RD





MARCH 17, 2006

David Woosley
City of Lawrence Traffic Engineer
P.O. Box 708
6 E 6th Street
Lawrence, KS 66044

RE: Southbound Left Turn Movement at 34th Street and Iowa Street

Dear Mr. Woosley,

We are experiencing a significant problem with delays for our employees and customers who are turning from the North on Iowa, left on 34th Street and into our business. We are waiting to make the turn for what seems an extreme amount of time. The wait is so long that anyone who needs to make this turn on a regular basis is just running the light. By the way, I am not advocating enforcement of the wait, but rather a change of the traffic control programming or timing or both.

This is to request your review and consideration of traffic signal timing and/or programming changes concerning the eastbound left turn movement. I have been informed by my engineer that there are options to consider. From what I have heard, a "protective-permissive left turn movement" would do much to help the problem.

Thank you for your attention to this problem. I may be reached at 843-7700 if you have any questions of me. My engineer is BG Consultants Inc. and they are also available to discuss my problem.

Sincerely,

A handwritten signature in black ink that reads "Miles E. Schnaer".

MILES E SCHNAER
President