

## TV Inspection Hobbs Park Stadium

The Utility Department completed video inspection of an 8" VCP sewer line. The sewer line starts with a manhole just southwest of the baseball stadium at Hobbs Park and flows west, and then takes a hard left to the south to city manhole SE311220-025. The line is in poor condition and the TV camera could not make it through the bend in the line. See map and photos attached. A copy of the video is available on disk for you.

Bob Brower/Utility Field Operations Manager  
832-7821



Photos from MH SE311220-025 going north to bend in line



Severe Root Intrusion



Inspection stopped where line bends 97 feet north of MH SE311220-025

Photos from MH at Hobbs Park Baseball Stadium headed west



Service connection 2 feet outside of Hobbs Park Manhole



TV inspection west from manhole in Hobbs Park

Photos from MH at Hobbs Park Baseball Stadium headed west



94.7 feet west of manhole



98.6 feet west of manhole



Photos from MH at Hobbs Park Baseball Stadium headed west



122.2 feet west of manhole



133.1 feet west of manhole

Photos from MH at Hobbs Park Baseball Stadium headed west



140.8 feet west of manhole/also severe sag in line



142.8 feet west of manhole

Photos from MH at Hobbs Park Baseball Stadium headed west



170.6 feet west of manhole/pipe separated allowing root growth



191.3 feet west of manhole/offset joint

Photos from MH at Hobbs Park Baseball Stadium headed west



194.4 feet west of manhole/pipe bends to the south



197.5 feet west of manhole/ pipe bends again- pipe bend separated  
Camera could not make it through the bend