

AGENDA: TSC 10/5/15

ITEM NO. 2: Consider establishing TRAFFIC CONTROL on Bauer Lane at Bauer Farm Drive.

Staff Report:

1. The intersection of Bauer Farm Drive & Bauer Lane is a "T" intersection; however, the commercial property on the north side of the street has constructed a driveway at the intersection directly in-line with Bauer Lane.
2. There have not been any reported crashes at the intersection; however, recessed angle-parking on the southwest corner of the intersection restricts the sight distance of northbound traffic.
3. It is recommended that a YIELD sign be installed for northbound traffic.

MINUTES: TSC 10/5/15

ITEM NO. 2:

Consider establishing TRAFFIC CONTROL on Bauer Lane at Bauer Farm Drive.

Woosley reviewed the information provided in the staff report.

Public Comments:

No public comment.

Commission Discussion:

Commissioner Koprince stated that he supported the request.

MOTION BY COMMISSIONER KOPRINCE, SECOND BY COMMISSIONER STORM, TO RECOMMEND ESTABLISHING A YIELD SIGN FOR NORTHBOUND TRAFFIC ON BAUER LANE AT BAUER FARM DRIVE; THE MOTION CARRIED, 8-0.



Future park (undeveloped)



Overland Dr

Champion Ln



Bauer Farm Dr

Bauer Farm Dr

Wakarusa Dr

40

W 6th St

Bauer Ln

Kirk Ln

Divilbiss Pl