David Woosley

From: Lauren Reinhold [reinhold@immigrationandtax.com]

Sent: Sunday, October 19, 2008 10:15 PM

To: David Woosley; David Woosley

Cc: lauren@sunflower.com

Subject: Petition regarding need for changes at Peterson and Arrowhead

Attachments: 20081019220011.pdf; 20081019220027.pdf; 20081019220043.pdf; 20081019220057.pdf;

20081019220112.pdf; 20081019220127.pdf; 20081019220143.pdf; 20081019220159.pdf; 20081019220222.pdf; 20081019220302.pdf; 20081019220319.pdf; 20081019220333.pdf; 20081019220347.pdf; 20081019220405.pdf; 20081019220433.pdf; 20081019220502.pdf

Mr. Woosley-

Here is our petition and 99 signatures. Please put this on the agenda for November 3, 2008. 12 pages of signatures are attached. I will bring the originals to the meeting, unless you require them sooner

Lauren E. Reinhold 520 Brentwood Drive 785-760-2114

Attorney at Law

Attorney at Law P.O. Box 664 16 East 13th Street Lawrence, Kansas 66044 (785) 842-3222 (785) 856-3791 (fax)

reinhold@immigrationandtax.com www.immigrationandtax.com

PLEASE NOTE OUR OFFICES HAVE MOVED TO A NEW LOCATION as of 1/1/08

This message is sent by a law office and is generally subject to confidentiality and privilege. However, please be aware that confidentiality is not guaranteed on any messages sent via any electronic means. Destroy this message and inform the sender if you are not the intended recipient. Please inform the sender if you wish for no further communication by electronic means. Any disclosure, reproduction or transmission of this e-mail or its contents is strictly prohibited without specific authorization from the sender.

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between Iowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of I-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road at all.
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the intersection. During crossing hours, a police officer sometimes situated nearby and hands out many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians must cross the street very defensively and this is difficult for families with children (often including, bikes, scooters and strollers).

Printed Name	Date	Address
LANA LAFLEN	10-18-08	505 Arow Land Dr.
MATRIEW RENGER	10-18-08	SOI ARROWHEAD DR
Dirok Rundle	10-18-0	8 54 Durhan
Rock + Hollow	10/13/3	401 Arranheed Dr.
MARY HALLORAN	10/18/08	HOI Arrowhead Dr.
anxing A Willege	10115/08	901 Augor No. 1 D
Amy Tharp	10 8 08	413 Arrowhead Dr
	MATTER RESPETS MATTER RESPETS DINOK RUND/E ROCKILL HORRAN MARY HALLORAN CANNIG A Willeyin	MATRIER RENTER 10-18-08 1) WOR RUND/E 10-18-08 ROCKEL HORRAN 10/18/08

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between Iowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of I-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road at all.
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT.
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the intersection. During crossing hours, a police officer sometimes situated nearby and hands out many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians must cross the street very defensively and this is difficult for families with children (often including, bikes, scooters and strollers).

Signature	Printed Name	Date	Address
agaga	JERany CoopeR	10-10-08	GOU BAITIY DR
ag your	CATHRYN COOPER	10-10-08	ECHBELTA PR
	Anh Eruko	19/7/08	608 Bely Pr
Tis MA	Tim Morstort	10/17/08	3003 Bently Circle
July Worsterf	Julie Mostorf	10/17/08	3003 Bently Cir
Of leve,	JEFF REELE	p/17/06	548 BENTLY DR.
Liky	Jessica Glendenin	9 10-18-08	508 Bently P
d			<u> </u>

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between Iowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of I-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road at all.
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT.
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the
 intersection. During crossing hours, a police officer sometimes situated nearby and hands out
 many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians
 must cross the street very defensively and this is difficult for families with children (often
 including, bikes, scooters and strollers).

Signature	Printed Name	Date	Address
Heidi Theler	uan Heidi Hallman	10/18/08	Sof Bently Dr.
	- HARL WELLE	rev 18 OKT	10 316 BENILY DX.
Regle Mort	ing Charles Martin	nez 10/18/	18528 Bently Dr.
Komoro Si			108 3911 Burke Dri
144	1 ALIGIA HAN	NA 10-13-2	000 540 BENTLY DR.
A Clark		mre 10-19	
	2 HADON Rey	- 10.18	ac 544 Boath AR
			΄ λ

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between Iowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of I-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road at all.
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT.
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the intersection. During crossing hours, a police officer sometimes situated nearby and hands out many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians must cross the street very defensively and this is difficult for families with children (often including, bikes, scooters and strollers).

Signature	Printed Name	Date	Address
M. pauteur Kennany	Maureen Kennedy	10-15-08	50+ Arrowland Drive
Clara Westshar	Chara Westital		500 several wind wine
lest org	Leslie O'Neil	10 15 08	409 Arracherd
hopa	STURNT O'NOL	10/15/08	409 ARROWHERD DR.
· suy Hey	oay HYNN	10/5/05	grandahelden live
Mally	JOHN KELLY	10/5/08	CIRANDONI Idra CROSS
M: K-1	MECHAEL KENNEDT	10/15/08	504 ARROWHEAD DR.

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between Iowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of 1-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to
 detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road at all.
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT.
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the intersection. During crossing hours, a police officer sometimes situated nearby and hands out many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians must cross the street very defensively and this is difficult for families with children (often including, bikes, scooters and strollers).

Signature	Printed Name	Date	Address	174
m Marion Ce	ogus MALION LASA	UPZ 10-9.8	8 UNITLOY	/
Lavina Va	Down L AVINA VAS	July 10-9-	DE LONIT 10°	7_
Friedaan	dres Frieda An	JES 10-9	08 unit 10	2 01
Tota C Wils	on Rita C Wils	on 10-9-0	2930 Pete	erson Kd
Ann Shas	yer Ann Shaf	fer 10-10	0-08 2,430 tel	+Son TYTH
w.m. yes	williamm Nudsor	10-10-0	8 2930 Peterso	m#1
M. E. Richard	le M.E. Richar	de 10-11-	06 2930 Peterson Re	d.#G

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between Iowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of I-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to
 detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road at all
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT.
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the intersection. During crossing hours, a police officer sometimes situated nearby and hands out many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians must cross the street very defensively and this is difficult for families with children (often including, bikes, scooters and strollers).

Signature	Printed Name	Date	Address	14
Bartana & dest	Barbaras	Skeet 10-11-	or 2930 Petersonk	d F
Mary a. Boys	CMARYA	. BOYER	18 2930 PETEYSONRI #1	19-2
			2930 Ptersonkd out X	
naomi Litte	IVACMIL	The 10-11	08 2930 Relievo Rdaft	W
Mildred Marris	MILdredmon	Pr18 10-11-	08 2930 Reterson & ap 7	1
Dous Welson	DOR'S Wilso	000 10-11-0	008 2930 Peterson Re	2 5

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between Iowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of 1-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road at all.
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the
 intersection. During crossing hours, a police officer sometimes situated nearby and hands out
 many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians
 must cross the street very defensively and this is difficult for families with children (often
 including, bikes, scooters and strollers).

Signature	Printed Name	Date	Address	
Roberta Hol	RobertuHale	10-12	2930 Peter	150 N #0
Wedley Gramm	a WESLEY Gramme	10 416	2930 Peteron	Pd.
//	Braun KA+H RYN		10-4 2930 Pater	en Rd M
Joan Baker	JOAN BAKE	10-114	t 2930 Peterson	RAR
fish out				
m	Melissa Anderso	n 10/14/0	8 628 Stoney	ate Ct-
Both Brillege	Both Brubeck	10/14/0	8 3814 Hill Sing	Circle

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between lowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of I-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to
 detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road at all.
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT.
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the intersection. During crossing hours, a police officer sometimes situated nearby and hands out many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians must cross the street very defensively and this is difficult for families with children (often including, bikes, scooters and strollers).

Signature	Printed Name	Date	Address
Palana Nover	Berbara Novor	10-14-08	3105 Tomahawk Dr.
Semma CVI svom	Jenna C Viscomi	1014-08	3208 Longhom M-
The Ruchinham	Paige Buckingham	10-14-08	84N Michigan St.
Dr. Bringard	t Lori brungard	+ 10/14/0	8 2004 Bently U.
Kun Hedly	Sherri Dedloff	10/14/08	360 Rivervices Pd
Lawrereganhold	Lauren E Reinhold	10/14/00	520 Brentwood Dr.

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between Iowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of I-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to
 detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road at all.
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the
 intersection. During crossing hours, a police officer sometimes situated nearby and hands out
 many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians
 must cross the street very defensively and this is difficult for families with children (often
 including, bikes, scooters and strollers).

	Signature	Printed Name	Datç	Address
(Levan Julyn	Lisan Swoger	199/08	623 Bently Drive
1	Begge	Beely Check-king	10/10/08	3006 Berthy Circle
	Stran Shaley	Alicia Smiler	to (10 (08	640 Bently
	Comp	ANT RIFFEL	19/10/08	3009 Carrington in
	Ralle Parit	Robbie Derrit	10/12/08	553 Arrewised

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between Iowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of I-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road at all.
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT.
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the intersection. During crossing hours, a police officer sometimes situated nearby and hands out many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians must cross the street very defensively and this is difficult for families with children (often including, bikes, scooters and strollers).

Signature	Printed Name	Date	Address
Cindula Della	Andria Deulin	10/14/08	601 Brentwood Dr.
Valerce Bido	Valorie Bido	10/14/08	3148 Tokahawk Dr
Lindi Branderburge	Linda Brandenburger	10/14/08	3100 Riverview Rd.
Desthird Shine	HEATHER SHIPE	10/14/08	333 Cattleman Trail
Nijolette Bearet	Nicolette Bennett	10/14/208	609 Brentwood Dr
A-Ma	OHRIS MERRILL	10/14/08	3771 Hurringson ES.
	Scott A. BEER		Loot Durhan Court
Du applima	Jmi Appleman	10/14/08	3509 Eagle Passet

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between Iowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of I-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road at all.
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the
 intersection. During crossing hours, a police officer sometimes situated nearby and hands out
 many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians
 must cross the street very defensively and this is difficult for families with children (often
 including, bikes, scooters and strollers).

Signature	Printed Name	Date	Address
Stace al heat	Stacey Collicatt	10/19/08	412 Arrowherd Dr
Mesa Stolegal	Pettingill, Nathan	1800 000 2006	408 A110mlusc)
Kathy Pierce	Kathy Pierre	10/18/08	325 Arrow heid Dr.
Petral Homen	Adrick K Rosencrants	10/18/08	321 Arrow how DR
- as W/ 13	Larry MELIN	10/18/008	317 Avrow head Dr
12in 21n	Diane R. Fourny	10/18/2008	8 2916 Mocres n Dr
	N.	,	

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between Iowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of 1-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road at all.
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT.
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the intersection. During crossing hours, a police officer sometimes situated nearby and hands out many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians must cross the street very defensively and this is difficult for families with children (often including, bikes, scooters and strollers).

	Signature	Printed Name	Date	Address
	Mary a Lade	Mary A. Lake ANGULA Closton Elen Brungardt	10/16/05	3001 Bently Ct. (3004 Bently Ct.
deploy	Bonhold	LaurenEReunhold	10-18-08	500 Brentwood
5	Certe	Kent Clasen	10-18-08	520 Brentwood

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between Iowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of I-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road at all.
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT.
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the
 intersection. During crossing hours, a police officer sometimes situated nearby and hands out
 many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians
 must cross the street very defensively and this is difficult for families with children (often
 including, bikes, scooters and strollers).

Signature	Printed Name	Date	Address
Ronda Morgison	Ronda Morgison	10/15/08	601 N. Stowe Ct
ffling 1	JOSEPH W. MORGESIN	10/15/08	GOIN Stone Cr.
Loma Jucker	Dona Tucker	10/19/08	525 Brotwed Dr.
andes	Chris Phillips	10/19/02	540 Brentwood Nr.
1/2	Andrew Tochtrop	10/19/08	53d Brentwood O.
	<u></u>		

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between Iowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of I-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road at all.
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT.
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the
 intersection. During crossing hours, a police officer sometimes situated nearby and hands out
 many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians
 must cross the street very defensively and this is difficult for families with children (often
 including, bikes, scooters and strollers).

Signature	Printed Name	Date	Address
Johnni Rosep	Stephane Rasys	10/14/28	1028 Carring for La
liver &	Angre Loures	10/110/08	2029 Carrington Lin Laurence, KS bill 049 aslovings

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between Iowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of I-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road at all.
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT.
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the intersection. During crossing hours, a police officer sometimes situated nearby and hands out many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians must cross the street very defensively and this is difficult for families with children (often including, bikes, scooters and strollers).

Signature	Printed Name	Date	Address
Aut man /	Scott Mª Kinney		/
Frond May hal	Rhond Marshal	10-11-08	541 Buntwood
Margaret Wen	A		
Mary Smillelin			3B Brentwad Dr
Son A-Williams	John A. Williams	16/12/08	568 Brestwool Dr
Cilea Mondel	Lilen Mandell	10[18]08	529 Brentwood Dr.
michie slige	Mickie Coilispie	10/19/08	560 Brentwood Br.

The Undersigned residents of the Deerfield area of Lawrence, Kansas support better traffic control on Peterson Road for the following reasons:

- Peterson Road is a very busy street with a speed limit of 40 miles per hour (though many drivers exceed the speed limit). There are no traffic lights or stop signs between Iowa and Kasold, a stretch of more than one mile through a residential neighborhood.
- The area has seen a significant increase in traffic due to residential development north of Peterson Road and south of I-70 between Monterey Way and Kasold.
- Many pedestrians, as well as children on bikes or scooters, cross Peterson Road at Arrowhead Drive to travel to and from Deerfield Park and Deerfield School. During good weather, numerous families travel this route on any given day. Sometimes, older children cross alone.
- There is a hill approximately 100 feet to the East of the intersection that makes it hard to
 detect the high-speed vehicular traffic approaching from that direction.
- It is not uncommon to have to race across the street to beat traffic that is traveling faster than allowed or expected. This is exacerbated by the fact that it is three lanes wide.
- During peak traffic times, it can be very difficult, nearly impossible, to cross Peterson Road
 at all
- A crossing guard is present when school begins and is let out, but this is a very short frame of time that the intersection sees pedestrian traffic. PLEASE NOTE: WE DO NOT SUPPORT LOSING OUR CROSSING GUARD, AS ADULT JUDGMENT IS STILL NEEDED AT THE SCHOOL CROSSING, DESPITE ANY PEDESTRIAN CONTROLLED TRAFFIC LIGHT.
- Many vehicles have been observed to violate traffic rules or ignore pedestrians at the intersection. During crossing hours, a police officer sometimes situated nearby and hands out many tickets to drivers who ignore the reduced speed limit. During all times, pedestrians must cross the street very defensively and this is difficult for families with children (often including, bikes, scooters and strollers).

Signature	Printed Name	Date	Address
James Min	James Morris	10/12/2008	552 Brentwood Dr
Cloutte water	a Olivette Watson	10/12/12008	BrentwoodDr
Cydy Barnett	CINDY BARNET	10/12/2008	548 Brentwood Pr.
Darry Trent	Danny Trent	10/12/08	533 Brendwood
Dawn Tren	t Dawn Trent	10/12/08	533 Brentwood
sal the	Sheryl Goering	10/12/08	537 Brentwood Dr.
Tu / Ha.	Kerin J. Goering	10/10/08	537 Brentwood Br.

Page 4C-6 2003 Edition

Section 4C.05 Warrant 4, Pedestrian Volume

Support:

The Pedestrian Volume signal warrant is intended for application where the traffic volume on a major street is so heavy that pedestrians experience excessive delay in crossing the major street.

Standard:

The need for a traffic control signal at an intersection or midblock crossing shall be considered if an engineering study finds that both of the following criteria are met:

- A. The pedestrian volume crossing the major street at an intersection or midblock location during an average day is 100 or more for each of any 4 hours or 190 or more during any 1 hour; and
- B. There are fewer than 60 gaps per hour in the traffic stream of adequate length to allow pedestrians to cross during the same period when the pedestrian volume criterion is satisfied. Where there is a divided street having a median of sufficient width for pedestrians to wait, the requirement applies separately to each direction of vehicular traffic.

The Pedestrian Volume signal warrant shall not be applied at locations where the distance to the nearest traffic control signal along the major street is less than 90 m (300 ft), unless the proposed traffic control signal will not restrict the progressive movement of traffic.

If this warrant is met and a traffic control signal is justified by an engineering study, the traffic control signal shall be equipped with pedestrian signal heads conforming to requirements set forth in Chapter 4E. Guidance:

If this warrant is met and a traffic control signal is justified by an engineering study, then:

- A. If at an intersection, the traffic control signal should be traffic-actuated and should include pedestrian detectors
- B. If at a nonintersection crossing, the traffic control signal should be pedestrian-actuated, parking and other sight obstructions should be prohibited for at least 30 m (100 ft) in advance of and at least 6.1 m (20 ft) beyond the crosswalk, and the installation should include suitable standard signs and pavement markings.
- C. Furthermore, if installed within a signal system, the traffic control signal should be coordinated.

Option:

The criterion for the pedestrian volume crossing the major roadway may be reduced as much as 50 percent if the average crossing speed of pedestrians is less than 1.2 m/sec (4 ft/sec).

A traffic control signal may not be needed at the study location if adjacent coordinated traffic control signals consistently provide gaps of adequate length for pedestrians to cross the street, even if the rate of gap occurrence is less than one per minute.



City of Lawrence, Kansas Traffic Engineering Division Traffic Signal Warrant Worksheet



Location: Arrowhead Drive & Peterson Road Date: 19-20 August 2008

Time	Peterson Road							Arrowhead Drive								Grand	Warra	Warrant Met						
Period		EB			EB		WB			WB	Total		NB			NB		SB			SB	Total	#1a	#1b
12-01		8			8		53			53	61		1			1		2			2	64		
01-02		6			6		21			21	27		0			0		2			2	29		
02-03		3			3		8			8	11		1			1		0			0	12		
03-04		6			6		11			11	17		0			0		5			5	22		
04-05		11			11		1			1	12		0			0		5			5	17		
05-06		41			41		15			15	56		5			5		20			20	81		
06-07		111			111		49			49	160		8			8		52			52	220		
07-08		204			204		152			152	356		19			19		139			139	514	1	
08-09		144			144		130			130	274		12			12		68			68	354		
09-10		104			104		78			78	182		2			2		25			25	209		
10-11		96			96		100			100	196		10			10		36			36	242		
11-12		116			116		112			112	228		14			14		60			60	302		
12-01		146			146		141			141	287		8			8		30			30	325		
01-02		159			159		135			135	294		22			22		38			38	354		
02-03		121			121		128			128	249		7			7		41			41	297		
03-04		156			156		189			189	345		35			35		42			42	422		
04-05		145			145		216			216	361		22			22		48			48	431		
05-06		158			158		294			294	452		38			38		63			63	553		
06-07		130			130		172			172	302		27			27		68			68	397		
07-08		81			81		135			135	216		21			21		30			30	267		
08-09		99			99		115			115	214		16			16		35			35	265		
09-10		79			79		104			104	183		4			4		18			18	205		
10-11		67			67		57			57	124		8			8		7			7	139		
11-12		34			34		39			39	73		2			2		4			4	79		
Totals	0	2225	0	0	2225	0	2455	0	0	2455	4680	0	282	0	0	282	0	838	0	0	838	5800	1	0

The Manual on Uniform Traffic Control Devices Minimum Volume Requirements for 8 hours:

Warrant #1a: Main Street -- 350 Minor Street -- 105
Warrant #1b: Main Street -- 525 Minor Street -- 53

Speed Limit on Peterson Road = 40 mph

no Warramt #7, Crash Experience, met

no Warrant #2, Four Hour Volume, met

no Warrant #3, Peak Hour Volume, met

