

Description – Contracted Crack Sealing



Description – Contracted Crack & Joint Filling w/ "PolyPatch" on Monterey Way N of W 6th



Description – Contracted Microsurfacing/Patching w/ Pavement Markings in north Lawrence



Description – Contracted Microsurfacing/Patching w/ Pavement Markings in north Lawrence



Description - Contracted Milling and Overlay Patching on W 6th St as part of emergency repair and rehabilitation



Description - Contracted Milling and Overlay Patching on W 6th St as part of emergency repair and rehabilitation



Description – Condition of Bob Billings Parkway near Wagon Wheel Rd prior to Contracted Milling and Overlay Patching as part of Emergency Repair and Rehabilitation



Description – Bob Billings Parkway near Wagon Wheel Rd after Contracted Milling and Overlay Patching as part of Emergency Repair and Rehabilitation



Description – N 2nd St @ Lincoln St after Milling and just prior to Contracted Overlay as part of Emergency Repair and Rehabilitation in coordination w/ 2nd & Locust Project



Description – Louisiana St near 23rd St during Contracted Milling and Overlay Patching as part of Emergency Repair and Rehabilitation



Description – Louisiana St near 23rd St during Contracted Milling and Overlay Patching w/ Pavement Markings as part of Emergency Repair and Rehabilitation



Description – Contracted Milling & Overlay (Phase 1) on Atchison Ave near 31st St



Description – Contracted Milling & Overlay (Phase 1) on 30th St at Harrison Ave with coordinated concrete intersection work performed by Internal Street Division



Description – Contracted Milling & Overlay (Phase 1) on Nieder Rd from 31st St to 33rd St



Description – Contracted Milling & Overlay (Phase 1 "Add") on Missouri St near 11th St



Description – Concrete base repair patching on Emery Rd from 9th St to High Dr as part of Contracted Milling & Overlay (Phase 1 "Add")



Description – Completed Overlay & Pavement Markings on Emery Rd from 9th St to High Dr as part of Contracted Milling & Overlay (Phase 1 "Add")



Description – Curb & Gutter Removal & Replacement on 20th St west of Alabama St as part of Contracted Milling & Overlay (Phase 2)



Description – W 20th St near Mitchell St has been Milled after Curb & Gutter Removal & Replacement as part of Contracted Milling & Overlay (Phase 2)



Description – Condition of E 23rd St east of Harper Ave during Milling as part of E23rd St KLINK Milling and Overlay Project



Description – Condition of Inverness Dr from Bob Billings Pkwy to Clinton Pkwy prior to Contracted Concrete Rehabilitation