




Photo Album for: Lawrence Fire & Medical, KS Job 23571

August 16, 2010

Your new apparatus is now in production. This week your cab finished in fabrication, paint and today started on the cab line where cab related content is added. The chassis started in assembly while the pump house completed fabrication and was in a paint spray booth.

The body finished in fabrication and was staged to begin the paint process. Later this week you should see the cab merged with the chassis and pump house while the body continues in paint.



DSC03190



DSC03191



DSC03192



DSC03193



DSC03194



DSC03195



DSC03196




DSC03197




DSC03198



DSC03199



DSC03200



DSC03201



DSC03202



DSC03203



DSC03204



DSC03205



DSC03206



DSC03207



DSC03208




DSC03209



DSC03210



DSC03211



DSC03183



DSC03184



DSC03185



DSC03186



DSC03187



DSC03188



DSC03189