


The background is a collage of firefighting-related images. It includes a close-up of a firefighter's helmet and face mask, a fire truck with 'FIRE-RESCUE' written on its side, and firefighters in full gear working near a fire. The text is overlaid on this collage.

Photo Album for: Lawrence Fire & Medical, KS Job 23571 September 3, 2010

This week your apparatus finished on main assembly and begins alignment and initial testing. Once completed, reflective striping (when requested or as specified) will be added. Next week, third-party pump testing should begin, to be followed by the road test.

ITEM NO.	23571
TRUCK NO.	12017514
INTERNAL ORDER NO.	12018226
AERIAL NO.	
TORQUE BOX NO.	
V.I.N. NO.	011356
CHASSIS BY:	☒ PIERCE ☐ CUSTOMER
DEALER:	CONRAD
CUSTOMER:	LAWRENCE KS
C/M:	SIEBERS

DSC06135



DSC06136



DSC06137



DSC06138



DSC06139



DSC06140



DSC06141




DSC06142



DSC06143



DSC06144



DSC06145



DSC06146



DSC06147



DSC06148



DSC06149



DSC06150



DSC06151



DSC06152



DSC06153



DSC06154



DSC06155



DSC06156



DSC06157



DSC06158



DSC06159



DSC06160



DSC06161



DSC06162



DSC06163



DSC06164



DSC06165



DSC06166



DSC06167



DSC06168



DSC06169



DSC06170



DSC06171



DSC06172



DSC06173



DSC06174



DSC06175



DSC06176



DSC06177



DSC06178



DSC06179



DSC06180



DSC06181




DSC06182



DSC06183



DSC06184



DSC06185



DSC06186




DSC06187



DSC06188




DSC06189



DSC06190



DSC06191



DSC06192



DSC06193




DSC06194



DSC06195



DSC06196



DSC06197



DSC06198