

## **Existing Kentucky Street Watermain Photos**

Seeping of pipe joints during winter conditions – February 2009



Section of Existing 1922 10" Watermain From 2005 Main Break – 1700 Block of Kentucky

