

Photo Album for Lawrence, KS

Job 25394

June 29, 2012

Your new apparatus is now in production. This week the cab began fabrication while the pump manifold began in plumbing. The PUC body began fabrication with side panels in weld up. In the next report the cab should begin the paint process. Body side panels should be joined in fabrication.

Due to the Pierce plant July 4th holiday shutdown, your next scheduled report will be July 13th, 2012.



DSC06008



DSC06009




DSC06010



DSC06011




DSC06012



DSC06148



DSC06149



DSC06150




DSC06151



DSC06152



DSC06153



DSC06205



DSC06206



DSC06207