

Photographs: Watkins National Bank Building
1047 Massachusetts Street, Lawrence, KS



East Facade



South Facade




North Facade



West Facade




Window Detail: deteriorated paint



Window Detail: deteriorated paint



Window Detail: temporary sash repair



Restored Third Floor Window, east facade



Restored Attic Window, east facade